



# 4 L+J SHRIVER 445-808 3.046 A<sup>c</sup>  
 # 3-C " " " 1.10 A<sup>c</sup>  
 TRACTS 44+3-C ARE NOT CORRECTLY DRAWN AS THIS STOP  
 SEE THE SURVEY PLAT.  
 ST RT 7 NEEDS MOVED EAST

27-07AD-

NOTE "A" THIS PROPERTY IN THIS AREA IS NOT DRAWN  
 CORRECTLY SR 7 NEEDS TO BE MOVED EAST  
 TRACT #10 OWNED BY N TROYER ETAL @ 466-918  
 IS PARTLY IN THIS SECTION. SEE SURVEY PLAT  
 FOR PLACE MEANT.

**SALINE TWP.**  
**SECTION 18, 7, T. 9, R. 2.**  
**SCALE: 1"=200'**